SOUTH ELEVATION

SCALE: NO SCALE



GENERAL CONSTRUCTION NOTES FOR BUILDING ELEVATIONS

1. NOT USED
2. REMOVE EXISTING SEALANTS AT THE PERIMETER OF THE EXISTING DOORS AND WINDOWS. INSTALL NEW POLYURETHANE SEALANT.
3. REMOVE DETERIORATED STONE AS REQUIRED. REPAIR AND PATCH WITH JAHN RESTORATION PATCHING REPAIR MORTAR.
4. INSPECT EXISTING BRICK MASONRY UNITS. PROVIDE INVENTORY OF UNITS REQUIRING REPLACEMENT. REPLACE WITH UNIT TO MATCH EXISTING.
5. REPAIR STRUCTURALLY DAMAGED MASONRY WALLS AT LITEWELL
6. INSPECT EXISTING MORTAR JOINTS. PROVIDE INVENTORY OF DETERIORATED MORTAR JOINTS. REMOVE DETERIORATED MORTAR JOINTS. TUCKPOINT WITH TYPE N MORTAR TO MATCH THE COLOR OF THE EXISTING.
7. INSPECT EXISTING STEEL LINTELS FOR DETERIORATION. PROVIDE INVENTORY OF DETERIORATED LINTELS. REPLACE DETERIORATED LINTELS WITH NEW STEEL LINTELS.
8. REMOVE EXISTING IVY FROM BRICK FACADE AND MORTAR JOINTS.
9. EXISTING DOUBLE HUNG WINDOWS TO REMAIN.

Emeritus House
Historic Restoration
4450 Cedar Avenue
Cleveland Ohio, 44103

Robert P. Madison International, Inc
Architects . Engineers . Planners
2820 Euclid Avenue
Cleveland, Ohio 44115
Tel. 216-861-0185 Fax. 216-621-5708

Mechanical Engineer
POINT ONE DESIGN, LTD
Consulting Engineers
Tel: (440) 238-1800 Fax: (440) 238-1851

Developers:
PNA KEMETTIS LLC
Phillis Hensley
Association
4450 Cedar Avenue
Cleveland, Ohio 44103
Tel. 216-391-4443
Fax. 216-791-6425

Ohio Capital Corporation
for Housing
88 East Broad Street,
Columbus , OH 43215
Tel. 614-224-6448
Fax. 614-224-9462

Contractors:
Marous Brothers
Construction
1702 Joseph Lloyd Parkway
Willoughby, OH 44094
Cleveland, Ohio 44115
Tel. 440-951-3904
Fax. 440-951-3701

Building Managers
ABC Management
P.O. Box 228035
2387S Commerce Park
Cleveland, Ohio 44122
Tel. 216-591-0661
Fax. 216 -591-1162

REVISIONS		
NO.:	DATE:	REMARK:

DATE: 6-9-06
SCALE: 1/8"=1'-0"
DRAWN: RKM
CHECKED: RKM
PROJECT NO.: 0329

© ROBERT P. MADISON INT.

South Elevation

A-303